

FIG. 1 1000 APPARATUS A




FIG. 1 1100 APPARATUS B




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6
1016
~1000 APPARATUS




FIG. 7




FIG. 9




FIG. 8




FIG. 10




FIG. 11





FIG. 12



Digitized by srujanika@gmail.com

FIG. 13

GROUP NO.	1	2	3	4	5	...
LINE CONTROL PORTION NO.						
1014	X	—	—	—	—	...
1024	△	—	—	—	—	...
1034	—	○	—	—	—	...
1044	—	○	—	—	—	...
1054	—	○	—	—	—	...
1064	—	—	○	—	—	...
•	•	•	•	•	•	•
•	•	•	•	•	•	•
•	•	•	•	•	•	•

- NOT GROUP MEMBER
- GROUP MEMBER, UNDER NORMAL OPERATION
- X GROUP MEMBER, OPERATION STOP DUE TO FAILURE
- △ GROUP MEMBER, OPERATION STOP DUE TO FAILURE IN OTHER LINE INSIDE GROUP

09654089-090100